City of Memphis, Tennessee, The County of Shelby, Tennessee, Tennessee Hoops LLP 191 Beale Street Memphis, Tennessee 38103

COPE SUMMARY

Values Throughout Report Are Expressed in Millions of USD

PD: 83.37

Visit on 16 July, 2009

RiskMarkFire Hazard Score: 32.88Total Score: 87.58Percentile within Client/Account: 50Equipment Hazard Score: 1.60Potential Score: 87.58Percentile within Industry: 96Natural Hazard Score: 26.00Percent of Potential Score: 100%Percentile within FM Global: 93

Occupancy Hazard Score: 8.10

H. E. / Other Factors Score: 19.00

Recommendation Summary: No active recommendations exist

Occupancy

MFL:

Public Auditoriums, Convention Centers, Sport Arenas, and Country Clubs

What Does this Site Do?:

This multipurpose arena is used for sporting events, music concerts, large gatherings, etc. There is an associated Administration Building and parking deck.

Auditoriumns-AS Occupancy Comments:

This arena project costs \$250 million to build and took about 20 mo. to complete. This is a joint project involving the city, county, and public building authority. FedEx Corporation was a heavy supporter of this project. They also bought the naming rights. Their name is printed above the plaza entrance and also painted on the roof. This arena building is being called the FedExForum. There are 32 luxury suites which cost anywhere from \$99,000 cheapest up to \$249,000 most expensive at the Club Level. FedEx Corporation and First Tennessee Bank are the only company's that have a double suite situated at center court. Other party suites are also available for rent on a game day basis only. Total of 60 suites.

<u>Atypical Processes and Equipment</u>: This site is occupied 24 hr. at 365 days/yr. by several security guards, including at least two persons normally stationed at the main security guard post nearest to the Players Parking Garage. This site is also occupied 24/7 by at least one building engineer at all times.

Construction

Data in this section was directly calculated from available data for the individual buildings

BI: 11.18

Construction Type	Area (ft2)	%	# Stories Above Ground	# Basement Levels
Reinforced Concrete Construction	1,220,440	86	5	2
Concrete on Protected Steel	36,992	3	3	
Steel Deck (1) Type Construction	149,300	11	4	
Steel Deck (2) Type Construction	12,330	1	4	

Total Area 1,419,062 (ft2)

Protection

Automatic Sprinklers: Provided: 53 % Needed: 0 % Pumper Suction Reliable: No Description:

Index 000605.52-02 Account 01-39437 Order ID 0000845627-7 Factory Mutual Insurance Company (FM Global) has developed this report for insurance underwriting purposes. The report is provided to you for informational purposes only to reduce the possibility of loss to property by bringing to your attention certain potential hazards or conditions. You must make the decision whether to take any action. FM Global undertakes no duty to any party by providing this report or performing the activities on which it is based. The liability of FM Global is limited to that contained in its insurance policies.



Water Supplies: (Installed unless otherwise stated)					
Туре	Name	Static Pressure (psi)	Capacity (gallons)		
Public	City of Memphis	84.0	9,999,999,999.0		

Fire Pumps: (Installed unless otherwise stated)

Name	Pump Type	Driver Type	Flow (gpm)	Pressure (psi)	Speed
Fire Pump System	Horizontal	Electric Driver	2,000.0	65.0	1780

Fire Dept.: Paid

Watch Service: Present: Yes Plant Covered: 100 %

Intervals: Nights: 4 hours Days: 4 hours

Fire Detection System: Plant Covered: 1 % Connected to: Guardhouse,

Unapproved Proprietary Station

Natural Hazards

Flood

Presents a Hazard to Site? No

Earthquake

Presents a Hazard to Site? Moderate

Wind

Presents a Hazard to site? No

Water Tests for Fire Pumps/Water Supplies

Item	Туре	Date	Ву	Flow Rate (gpm)	P1* (psi)	P2* (psi)
FlowPoint	Gauge Location	Comments				
Fire Pump System	Pump Test	Jul 2009	FM Global Employee	0.0	85.0	172.0
pump header	fire pump house	churn only				
Fire Pump System	Pump Test	Feb 2009	Contractor	2,940.0	64.0	109.0
pump header	fire pump room	done by Moore Pump & Equipment				
Fire Pump System	Pump Test	Feb 2009	Contractor	1,915.0	75.0	142.0
pump header	fire pump room	done by Moore Pump & Equipment				
Fire Pump System	Pump Test	Feb 2009	Contractor	0.0	82.0	164.0
pump header	fire pump room	done by Moore Pump & Equipment				
Fire Pump System	Pump Test	Jan 2007	Contractor	3,039.0	70.0	116.0
Pump Header	Pump Guages			,	,	

Index 000605.52-02 Account 01-39437 Order ID 0000845627-7 Factory Mutual Insurance Company (FM Global) has developed this report for insurance underwriting purposes. The report is provided to you for informational purposes only to reduce the possibility of loss to property by bringing to your attention certain potential hazards or conditions. You must make the decision whether to take any action. FM Global undertakes no duty to any party by providing this report or performing the activities on which it is based. The liability of FM Global is limited to that contained in its insurance policies.



Item	Туре	Date	Ву	Flow Rate (gpm)	P1* (psi)	P2* (psi)
Fire Pump System	Pump Test	Jan 2007	Contractor	2,035.0	77.0	142.0
Pump Header	Pump Guages			,		
Fire Pump System	Pump Test	Jan 2007	Contractor	0.0	83.0	162.0
Pump Header	Pump Guages		·			
Fire Pump System	Pump Test	Nov 2005	Contractor	3,037.0	70.0	119.0
Pump Header	Pump Guages					
Fire Pump System	Pump Test	Nov 2005	Contractor	1,993.0	80.0	148.0
Pump Header	Pump Guages					
Fire Pump System	Pump Test	Nov 2005	Contractor	1,077.0	83.0	163.0
Pump Header	Pump Guages					
Fire Pump System	Pump Test	Nov 2005	Contractor	0.0	85.0	167.0
Churn	Pump Guages					
Fire Pump System	Pump Test	May 2005	FM Global Employee	0.0	90.0	165.0
Churn	Pump Guages					
Fire Pump System	Pump Test	Nov 2004	FM Global Employee	3,000.0	71.0	118.0
Pump Header	Pump Guages					
Fire Pump System	Pump Test	Nov 2004	FM Global Employee	2,500.0	75.0	136.0
Pump Header	Pump Guages		,			
Fire Pump System	Pump Test	Nov 2004	FM Global Employee	2,000.0	77.0	147.0
Pump Header	Pump Guages		,			
Fire Pump System	Pump Test	Nov 2004	FM Global Employee	1,000.0	81.0	165.0
Pump Header	Pump Guages		,			
Fire Pump System	Pump Test	Nov 2004	FM Global Employee	0.0	84.0	169.0
Pump Header	Pump Guages					
* Water/Combined Tests:	P1=Static; P2=Residual	-				

^{*} Pump Tests: P1=Suction; P2=Discharge

